

SECRET 25X1 (c) NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER Z-14051/83 Page $\underline{1}$ of $\underline{1}$ Attachment to NPIC/IEG (10/83) Copy 223 5 OCTOBER 1983 TANK PRODUCTION LUOYANG, CHINA (SWN) 25X1 1. SIGNIFICANCE: THIS IS THE FIRST CONFIRMATION OF TANK PRODUCTION AT LUOYANG. (SWN) 25X1 24 CANVAS-COVERED MEDIUM TANKS WERE NEAR A TRANSSHIPMENT 2. REMARKS: AREA INSIDE A NEWLY IDENTIFIED TANK ASSEMBLY FACILITY, LUOYANG TANK ASSEMBLY PLANT. THE SEPARATELY SECURED PLANT IS ALONG THE WEST EDGE OF LUOYANG BEARING PLANT AND IMMEDIATELY EAST OF LUOYANG TRACTOR PLANT DONGFANGHONG 1. BY ONLY THREE POSSIBLE TANKS WERE IN THE TRANSSHIPMENT AREA, INDICATING 25X1 A TANK SHIPMENT MAY HAVE TAKEN PLACE. IN ADDITION, TANK TURRETS WERE OBSERVED AT LUOYANG ARMS AND MINING MACHINERY PLANT. AT FOR THE FIRST TIME 25X1 LEAST SIX TANK TURRETS WERE ON A REJECT PILE UNDERNEATH A GANTRY CRANE NEAR THE CASTING/FOUNDRY BUILDING AT THE WEST EDGE OF THE PLANT. THE CONSTRUCTION OF THE TANK ASSEMBLY PLANT, WHICH BEGAN IN THE EARLY 1970'S, WAS PREVIOUSLY CONSIDERED AN EXPANSION OF THE BEARING PLANT. THE TANK ASSEMBLY FACILITY CONSISTS OF THREE LARGE FABRICATION/ASSEMBLY BUILDINGS (ONE WITH A PROBABLE FINAL ASSEMBLY WING), ONE LARGE SHOP BUILDING, ONE SHOP/FOUNDRY BUILDING, AND ONE RAIL-TO-ROAD TRANSSHIPMENT AREA. A LARGE SHIPPING AND RECEIVING AREA WITH NUMEROUS STORAGE BUILDINGS AND AN OPEN BULK MATERIAL YARD ARE IMMEDIATELY NORTH OF THE PLANT. A REVIEW OF IMAGERY FROM OCTOBER 1980 TO SEPTEMBER 1983 REVEALED THAT TANK PRODUCTION WAS POSSIBLY 25X1 WHEN 26 POSSIBLE ARMORED VEHICLES WERE UNDERWAY AS EARLY IN THE TRANSSHIPMENT AREA. TANK PRODUCTION HAS BEEN SUSPECTED IN THE LUOYANG AREA SINCE AT LEAST 1977, WHEN ONE CONFIRMED AND ONE PROBABLE TURRET CASTING MOLD WERE OUTSIDE THE CASTING/FOUNDRY BUILDING AT THE ARMS AND MINING MACHINERY PLANT. CASTING MOLDS WERE ALSO CONFIRMED HERE IN OCTOBER 1980. A RELATED TEST AREA. 25X1 LUOYANG ARMOR VEHICLE TEST TRACK AND RANGE . 2.6 NM SOUTHWEST OF THE ARMS AND MINING MACHINERY PLANT, WAS FIRST OBSERVED UNDER CONSTRUCTION IN 1979. THE TEST TRACK WAS PROBABLY OPERATIONAL BETWEEN DECEMBER 1982 AND APRIL 1983 WHEN ARMORED VEHICLE TRACKAGE WAS OBSERVED. 25X1 25X1 25X1 3. COORDINATES 34-40-30N 112-23-07E (S) COORDINATES 34-40-2IN 112-23-37E (S)

These notes have been prepared for briefing purposes only and should not be used for detailed analytical work. Their use should be restricted to the particular briefing board(s) they were prepared for and must be considered valid only for the reporting period as indicated by the date of issue.

25X1

WARNING NOTICE Intelligence Sources and Methods Involved COORDINATES 34-40-35N 112-22-33E (S) COORDINATES 34-41-09N 112-27-12E (S)

SECRET

25X1

(c) NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER

Page 1 of 1
Copy 22/

Attachment to

Z-14051/83

NPIC/IEG (10/83)

5 OCTOBER 1983

TANK PRODUCTION
LUOYANG, CHINA (SWN)

25X1

THIS IS THE FIRST CONFIRMATION OF TANK PRODUCTION AT LUOYANG. 1. SIGNIFICANCE: (SWN) 25X1 2. REMARKS: 24 CANVAS-COVERED MEDIUM TANKS WERE NEAR A TRANSSHIPMENT AREA INSIDE A NEWLY IDENTIFIED TANK ASSEMBLY FACILITY, LUOYANG TANK ASSEMBLY PLANT. THE SEPARATELY SECURED PLANT IS ALONG THE WEST EDGE OF LUOYANG BEARING PLANT AND IMMEDIATELY EAST OF LUOYANG TRACTOR PLANT DONGFANGHONG 1. BY ONLY THREE POSSIBLE TANKS WERE IN THE TRANSSHIPMENT AREA, INDICATING 25X1 A TANK SHIPMENT MAY HAVE TAKEN PLACE. IN ADDITION, TANK TURRETS WERE OBSERVED AT LUOYANG ARMS AND MINING MACHINERY PLANT. AT FOR THE FIRST TIME ON 25X1 LEAST SIX TANK TURRETS WERE ON A REJECT PILE UNDERNEATH A GANTRY CRANE NEAR THE CASTING/FOUNDRY BUILDING AT THE WEST EDGE OF THE PLANT. THE CONSTRUCTION OF THE TANK ASSEMBLY PLANT, WHICH BEGAN IN THE EARLY 1970'S, WAS PREVIOUSLY CONSIDERED AN EXPANSION OF THE BEARING PLANT. THE TANK ASSEMBLY FACILITY CONSISTS OF THREE LARGE FABRICATION/ASSEMBLY BUILDINGS (ONE WITH A PROBABLE FINAL ASSEMBLY WING), ONE LARGE SHOP BUILDING, ONE SHOP/FOUNDRY BUILDING, AND ONE RAIL-TO-ROAD TRANSSHIPMENT AREA. A LARGE SHIPPING AND RECEIVING AREA WITH NUMEROUS STORAGE BUILDINGS AND AN OPEN BULK MATERIAL YARD ARE IMMEDIATELY NORTH OF THE PLANT. A REVIEW OF IMAGERY FROM OCTOBER 1980 TO SEPTEMBER 1983 REVEALED THAT TANK PRODUCTION WAS POSSIBLY 25X1 UNDERWAY AS EARLY WHEN 26 POSSIBLE ARMORED VEHICLES WERE IN THE TRANSSHIPMENT AREA. (SWN) TANK PRODUCTION HAS BEEN SUSPECTED IN THE LUOYANG AREA SINCE AT LEAST 1977, WHEN ONE CONFIRMED AND ONE PROBABLE TURRET CASTING MOLD WERE OUTSIDE THE CASTING/FOUNDRY BUILDING AT THE ARMS AND MINING MACHINERY PLANT. CASTING MOLDS WERE ALSO CONFIRMED HERE IN OCTOBER 1980. A RELATED TEST AREA. , 2.6 NM SOUTHWEST LUOYANG ARMOR VEHICLE TEST TRACK AND RANGE 25X1 OF THE ARMS AND MINING MACHINERY PLANT, WAS FIRST OBSERVED UNDER CONSTRUCTION THE TEST TRACK WAS PROBABLY OPERATIONAL BETWEEN DECEMBER 1982 AND APRIL 1983 WHEN ARMORED VEHICLE TRACKAGE WAS OBSERVED. 25X1 25X1 25X1 3. COORDINATES 34-40-30N 112-23-07E (S) COORDINATES 34-40-2IN 112-23-37E (S) COORDINATES 34-40-35N 112-22-33E (S) COORDINATES 34-41-09N 112-27-12E (S) 25X1

WARNING NOTICE Intelligence Sources and Methods Involved

SECRET

These notes have been prepared for briefing purposes only and should not be used for detailed analytical work. Their use should be restricted to the particular briefing board(s) they were prepared for

and must be considered valid only for the reporting period as indicated by the date of issue.

25X1